## **SB-753 Completion Notification**

If a "Yes" box cannot be checked, state the reason in the Comments

After performing updates required under SB-753, complete and e-mail this Completion Notification (TP-7015) to: mb02905@kohler.com

1.	Generator Set Model:	section below.		
2.	Generator Set Serial Number:	Yes ☐ 7. Downloaded Event Log (History)? ☐ Did the Event Log (History) have any Coolant Los	s	
3.	Generator Set Hours:	Did the Event Log (History) have any Coolant Los Faults? If Yes, proceed to Step 8. If No, proceed Step 9.	to	
4.	Date Service Performed:	8. Inspected the exhaust hose?		
5.	Dealership that Performed the Service:	Wa's there any damage found inside the hose?		
		<ul> <li>9. Replaced the seawater pump impeller? Note impeller condition (select one below): Good Some wear Failed</li> </ul>		
6.	Service Performed by (Print/Type Technician's Name):	10. Verified that the seawater flow switch is installed?		
		<ul> <li>11. Inspected the freeze plugs?</li> <li>Any leaking freeze plugs?</li> </ul>		
Comm	ents:			



KOHLER CO., Kohler, Wisconsin 53044 Phone 920-457-441, Fax 920-459-1646 For the nearest sales/service outlet in the US and Canada, phone 1-800-544-2444 KOHLERPower.com