

NFPA Literature Kits

February 2017

| Model | Kit Number | Generator Manuals | | | | | Engine Manuals | | | | | Alternators | | NFPA Form |
|-------------|-------------|-------------------|-----------|----------------|---------|-------------------|----------------|-------------|---------|-------------|-------------|-------------|-------------|-----------|
| | | Installation | Operation | Wiring Diagram | Parts | Operation Service | Installation | Operation | Parts | Service | User | Operation | Operation | |
| KD800 60Hz | GM101565-KP | TP-5700 | TP-7070 | TP-7071 | TP-7064 | TP-7073 | 33508003101 | 33521029401 | TP-7052 | 33525087701 | 33502033801 | | | K-3322 |
| KD800 50Hz | GM101577-KP | TP-5700 | TP-7070 | TP-7071 | TP-7064 | TP-7073 | 33508003101 | 33521029401 | TP-7053 | 33525087701 | 33502033801 | | | K-3322 |
| KD900 60Hz | GM101561-KP | TP-5700 | TP-7070 | TP-7071 | TP-7064 | TP-7073 | 33508003101 | 33521029401 | TP-7052 | 33525087701 | 33502033801 | | | K-3322 |
| KD900 50Hz | GM101573-KP | TP-5700 | TP-7070 | TP-7071 | TP-7064 | TP-7073 | 33508003101 | 33521029401 | TP-7053 | 33525087701 | 33502033801 | | | K-3322 |
| KD1000 60Hz | GM101557-KP | TP-5700 | TP-7070 | TP-7071 | TP-7064 | TP-7073 | 33508003101 | 33521029401 | TP-7052 | 33525087701 | 33502033801 | | | K-3322 |
| KD1000 50Hz | GM101569-KP | TP-5700 | TP-7070 | TP-7071 | TP-7064 | TP-7073 | 33508003101 | 33521029401 | TP-7053 | 33525087701 | 33502033801 | | | K-3322 |
| KD1250 60Hz | GM101503-KP | TP-5700 | TP-7070 | TP-7071 | TP-7066 | TP-7073 | 33508003101 | 33521030001 | TP-7056 | 33525088301 | 33502033801 | TP-7075 | 33522939201 | K-3322 |
| KD1250 50Hz | GM101519-KP | TP-5700 | TP-7070 | TP-7071 | TP-7066 | TP-7073 | 33508003101 | 33521030001 | TP-7057 | 33525088301 | 33502033801 | TP-7075 | 33522939201 | K-3322 |
| KD1500 60Hz | GM101507-KP | TP-5700 | TP-7070 | TP-7071 | TP-7066 | TP-7073 | 33508003101 | 33521030001 | TP-7056 | 33525088301 | 33502033801 | TP-7075 | 33522939201 | K-3322 |
| KD1500 50Hz | GM101523-KP | TP-5700 | TP-7070 | TP-7071 | TP-7066 | TP-7073 | 33508003101 | 33521030001 | TP-7057 | 33525088301 | 33502033801 | TP-7075 | 33522939201 | K-3322 |
| KD1600 60Hz | GM101511-KP | TP-5700 | TP-7070 | TP-7071 | TP-7066 | TP-7073 | 33508003101 | 33521030001 | TP-7056 | 33525088301 | 33502033801 | TP-7075 | 33522939201 | K-3322 |
| KD1600 50Hz | GM101527-KP | TP-5700 | TP-7070 | TP-7071 | TP-7066 | TP-7073 | 33508003101 | 33521030001 | TP-7057 | 33525088301 | 33502033801 | TP-7075 | 33522939201 | K-3322 |
| KD1750 60Hz | GM101515-KP | TP-5700 | TP-7070 | TP-7071 | TP-7066 | TP-7073 | 33508003101 | 33521030001 | TP-7056 | 33525088301 | 33502033801 | TP-7075 | 33522939201 | K-3322 |
| KD1750 50Hz | GM101531-KP | TP-5700 | TP-7070 | TP-7071 | TP-7066 | TP-7073 | 33508003101 | 33521030001 | TP-7057 | 33525088301 | 33502033801 | TP-7075 | 33522939201 | K-3322 |
| KD2000 60Hz | GM101752-KP | TP-5700 | TP-7070 | TP-7071 | TP-7067 | | 33508003101 | 33521030301 | TP-7058 | 33525088601 | 33508003101 | TP-7075 | 33521018401 | K-3322 |
| KD2250 60Hz | GM101756-KP | TP-5700 | TP-7070 | TP-7071 | TP-7067 | | 33508003101 | 33521030301 | TP-7058 | 33525088601 | 33508003101 | TP-7075 | 33521018401 | K-3322 |
| KD2250 50Hz | GM101768-KP | TP-5700 | TP-7070 | TP-7071 | TP-7067 | | 33508003101 | 33521030301 | TP-7058 | 33525088601 | 33508003101 | TP-7075 | 33521018401 | K-3322 |
| KD2500 60Hz | GM101760-KP | TP-5700 | TP-7070 | TP-7071 | TP-7067 | | 33508003101 | 33521030301 | TP-7058 | 33525088601 | 33508003101 | TP-7075 | 33521018401 | K-3322 |