



### **Stator Service Kit 228261 Model 1750MBM25 (Specification 142104 Only)**

The stator service Kit is necessary to service the stator assembly on Kohler 1750 portable generators with specification number 142104. Models built to this specification utilized a stator (228259) and capacitor (228255) which are not available as service parts. Replacement of the stator on these units requires that the capacitor be changed to that supplied with the new stator. The stator included with the kit is NOT compatible with the capacitor originally installed in the generator. Failure to install the new capacitor during stator replacement will result in decreased generator output.

To install the Stator Service Kit, refer to the 1750 Service Manual (TP-5173). Follow the prescribed disassembly/reassembly procedure and refer to the wiring diagram for proper connection of components. **Be sure to follow all safety precautions listed at the front of the service manual during kit installation.**

#### **Parts Listing**

<b>Part No.</b>	<b>Description</b>	<b>Qty.</b>
228136	Capacitor	1
228137	Stator Assembly	1