

PARTS BULLETIN

Original Issue Date: **10/01**

Models: **17RY and 22RY**

Market: **Residential/Commercial**


Subject: **Temperature Switch Part Number and Location Change**

As a product improvement, Kohler has changed the part number and location of the temperature switch on the above models.

If replacing switch part number 255241 in the old location, order switch part number GM22525 and install

it in the new location directly into the cylinder head. The older sender remains in the thermostat housing as a plug.

Please note this change in parts catalog TP-6007 5/01, 17/22RY, page 23, item 47.



Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							