

SERVICE BULLETIN

Original Issue Date: 5/95  
Model: 50-100ROZJ  
Market: Industrial  
Subject: Piston Pin

When performing major engine work on the following engines, bearing engine serial numbers 390254-430251 replace all piston pins. An improved piston pin has been developed for these engines.

Model	John Deere Engine
50/60ROZJ	4039TL
80ROZJ	TO6059T
100ROZJ	6059TF

Replace all engine piston pins in the generator engine serial number range (390254-430251) with redesigned piston pins at the following times:

- 1. When piston pin(s) causes engine failure.
- 2. At time of major overhaul.

Continue to use Kohler part number 223488 for replacement piston pins.

Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							